



Hydrochloric Acid Analyze (HCl)

No	Properties	Value	Result
1	Content HCl	32 - 33%	33%
2	Free Cl, Br (ppm)	Max 20	Under 20
3	Fe (ppm)	Max 5	0.5
4	Heavy metals (ppm)	Max 2	Under 2
5	Sulfate (ppm)	Max 100	Under 100
6	Sulfites (ppm)	Max 50	Under 49
7	Arsenic (ppm)	Max 1	Under 1
8	Mercury (ppm)	Max 1	Under 0.25
9	Copper (ppm)	Max 1	Under 0.9
10	Lead (ppm)	Max 1	Under 1
11	Appearance (ppm)	Colorless and transparent	Approved

Main office: Homa building, Nafisi str, Tehran/Iran

Website: www.Iranhcl.com

Tel: +98(21)56512779

Whatsapp: +989141032292

Email: tiz_aa@yahoo.com